

Message

---

**From:** Maraldo, Dean [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=8076BC00B04C4AC1A4E608822A0DED7D-DMARALDO]  
**Sent:** 3/16/2017 3:00:58 PM  
**To:** Nowicki, Tom [TNowicki@mmsd.com]  
**Subject:** RE: Milorganite(r)

Tom: I have one outstanding item in my notes, in terms of information requested during the inspection. I asked Mr. Jacob Holbert for copies of recent manual dryer temperature field measurements. I understand that operators did not record the manual dryer temp measurements until recently. If these records exist I would appreciate copies to complete my inspection record.

Thanks,  
 Dean

---

Dean Maraldo  
 Water Enforcement & Compliance Assurance Branch  
 U.S. EPA - Region 5  
 77 West Jackson Blvd. (WC-15J)  
 Chicago, Illinois 60604  
 ph: (312) 353-2098  
 fax: (312) 385-5394  
 e-mail: [maraldo.dean@epa.gov](mailto:maraldo.dean@epa.gov)  
<http://www.epa.gov/enforcement/>

---

**From:** Nowicki, Tom [mailto:TNowicki@mmsd.com]  
**Sent:** Wednesday, March 15, 2017 6:48 AM  
**To:** Maraldo, Dean <Maraldo.Dean@epa.gov>  
**Subject:** Milorganite(r)

Good morning Dean –

I hope your return to the Chicago area was safe. I have attached the safety data sheet that you requested for the dust suppressant.

Tom Nowicki  
 Milorganite®  
 414-225-2243